



Brief of Accident (Continued)

LAX98LA058  
File No. 1206

12/20/1997

TRUCKEE, CA

Aircraft Reg No. N5058L

Time (Local): 10:15 PST

---

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF  
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) ENGINE ASSEMBLY,CONNECTING ROD BOLT - SHEARED
2. (C) ENGINE ASSEMBLY,CONNECTING ROD - FAILURE

-----  
Occurrence #2: FORCED LANDING  
Phase of Operation: EMERGENCY LANDING AFTER TAKEOFF  
-----

Occurrence #3: NOSE OVER  
Phase of Operation: LANDING - ROLL

Findings

3. (F) TERRAIN CONDITION - SNOW COVERED

Findings Legend: (C) = Cause, (F) = Factor

---

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.  
internal mechanical failure of the engine due to a progressive failure of the No. 3 connecting rod assembly. A contributing factor was the snow pack which covered the only accessible emergency landing area.