National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 06/08/2005

DFW05LA041

File No. 17724	12/19/2004	Texas City, TX	Aircraft Reg No.	N992RS	Tim	ne (Local): 12:42 CST
	1 None Personal	IA	Crew Pass	Fatal 0 0	Serious 1 1	Minor/None 0 0
	La Porte, TX Local Flight Off Airport/Airstrip	Condition of Light: Day Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: None Visibility: 10.00 SM Wind Dir/Speed: 350 / 009 Kts Temperature (°C): 17 Precip/Obscuration: None / None				
Pilot-in-Command Age: 30 Certificate(s)/Rating(s) Private; Single-engine Land; Single-engine Sea; Glider nstrument Ratings Airplane			Flight Time (Hours) Total All Aircraft: 370 Last 90 Days: Unk/Nr Total Make/Model: Unk/Nr Total Instrument Time: UnK/Nr			

A witness located adjacent to the accident site reported observing the 370-hour private pilot flying inverted at an altitude of approximately 50 feet above ground level for a distance of 250 yards. As the pilot attempted to roll the airplane upright, one of the wings impacted the ground. Examination of the airframe did not reveal any anomalies that could have contributed to the accident.

Brief of Accident (Continued)

DFW05LA041

File No. 17724 12/19/2004 Texas City, TX Aircraft Reg No. N992RS Time (Local): 12:42 CST

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: MANEUVERING

Findings

1. (C) AEROBATICS - ATTEMPTED - PILOT IN COMMAND

2. (C) ALTITUDE - LOW - PILOT IN COMMAND

3. (C) ALTITUDE/CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

4. TERRAIN CONDITION - OPEN FIELD

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Cafety Board determines the probable sayso(s) of this assident as follows

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. The pilot's failure to maintain clearance with terrain while performing aerobatics at a low altitude.