

Brief of Accident (Continued)

FTW95FA232

File No. 907

06/06/1995

JOAQUIN, TX

Aircraft Reg No. N8754

Time (Local): 19:10 CDT

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING

Findings

1. (C) AEROBATICS - PERFORMED - PILOT IN COMMAND
 2. (C) ALTITUDE - INADEQUATE - PILOT IN COMMAND
 3. (C) STALL - INADVERTENT - PILOT IN COMMAND
-

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: DESCENT - UNCONTROLLED

Findings

4. OBJECT - TREE(S)

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.
THE PERFORMANCE OF AEROBATICS AT LOW ALTITUDE AND THE INADVERTENT STALL.